


Ultrasonic Thickness Gauge IPX-251H



Contents

- 1 Technical Specification
- 2 Standard Delivery
- 3 Optional Transducers
- 4 Overview of the Display Unit
- 5 Keypad Functions
- 6 Display Screen
- 7 Basic Gauge Operations
 - 7.1 Switch on
 - 7.2 Probe Zero
 - 7.3 Backlight
 - 7.4 Parameters setting
 - 7.4.1 Measurement Mode
 - 7.4.2 Other parameters setting
 - 7.4.2.1 Velocity Rate
 - 7.4.2.2 Resolution
 - 7.4.2.3 Calibration
 - 7.4.3 Memory
 - 7.4.3.1 Memory Unit
 - 7.4.3.2 Memory Read
 - 7.4.3.3 Delete All Memory
 - 7.4.4 Date Transfer
 - 7.4.5 Function
 - 7.4.5.1 Power Off
 - 7.4.5.2 Gain adjustment
 - 7.4.5.3 Default
 - 7.4.5.4 Information

1. TECHNICAL SPECIFICATIONS

Measurement range	0.65mm 400.0mm	
Resolution	0.01mm(0.001), 0.1mm (0.01)	
Velocity range	1000m/s 9999m/s	
Measurement rate	4 /s and 10/s in fast mode	
Average mode	2 to 9 times average measurement	
Limited setting	With Low-high indication and alarm	
Measuring Units	Mm / inch	
Memory	Memory of 5000 readings with location number	
Data output	USB to PC	
Display	128×64 LCD with back light	
Battery	2 x AAA Batteries	
Operating temperature	-20°C +50°C	
Measuring temperature	-20°C +350°C (according to the probes)	
Dimensions	116mm L ×64mm W ×27mm H	
Weight	0.22kg (including batteries)	


2. STANDARD DELIVERY

- Main Unit
- Standard 5MHZ transducer
- 75ml Couplant
- Build-in calibration block
- Software and USB cable
- Carrying case Operating manual
- Certificate

3. OPTIONAL TRANSDUCERS

Model	Frequency	Range	Temperature
D5008	5.0MHz	0.8mm ~ 300mm	<60°C
D5113	5.0MHz	2.0mm ~ 200mm	<350°C
D7006	7.5MHz	0.65mm ~ 50mm	<60°C
D7004	10.0MHz	0.65mm ~ 20mm	<60°C
D2012	2.0MHz	3.0mm ~ 400mm	<60°C

4. OVERVIEW OF THE DISPLAY UNIT



- 1. LCD Screen
- 2. Key Pad
- 3. Battery Pack
- 4. Transducer Port
- 5. Test Block with 4mm

5. KEYPAD FUNCTIONS



	Function
AT PA	- On/ Off Key
(0)	- Esc. Menu
	- Menu Key
MENU	- Confirm Key
	- Up Arrow Key
•	- Backlight Key (Under the measurement)
7	- Down Arrow Key
V	- Calibration Key (Under the measurement)
	- Left Arrow key
SAVE	- Storage Key (Under the measurement)
	- Right Arrow Key
MEM	- Read data (Under the measurement)

6. DISPLAY SCREEN



- 1. Measuring Symbol
- 2. Battery Life
- 3. Current Velocity
- 4. Current Transducer model
- 5. Measurement Value and Measurement Mode
- 6. Current memory location

7. BASIC GAUGE OPERATIONS

7.1 Switch on

Press to turn on the gauge. The gauge will flash the series and version number.

7.2 Probe Zero

The gauge automatically zero's the transducer thus eliminating the need to zero. The gauge will switch into the measurement mode directly.

Make sure the transducer is not coupled to the test piece when the gauge is first turned on and that there is no coolant on the end of the transducer. The transducer should also be at room temperature, clean without any noticeable wear.

7.3 Backlight

Press



to turn on / off the backlight.

7.4 Parameters setting

7.4.1 Measurement Mode

Press to select measurement mode settings

Press



or 🔻

to select the type of measurement mode.

IPX-251H Ultrasonic Thickness Gauge offers two measurement modes; they are T-E Mode and Scan:

T-E Mode

- 1. STANDARD For normal measurement.
- 2. MINIMUM The gauge will measure and display the minimum measured thickness during one measurement process. Useful for measuring the thickness of curve surfaces or pipe.
- 3. DIFFERENCE The gauge will display a thickness value as an absolute number of what has been inputted. For example, input value = 5.00mm and the real thickness is 5.03mm, the display will show diff 0.03mm. If the real value is 4.97 mm, the gauge will display, -0.03mm.
- 4. AVERAGE The gauge will display the average thickness of 2-9 measurements
- LIMITS The gauge will alarm to alert low or high limits via an audible sound.

E-E Mode The Echo to Echo option allows you to make measurements between two consecutive back wall echoes. Therefore, a good usage of the Echo to Echo option is for measuring through coatings to measure only the true metal thickness.

SCAN The gauge will alarm for each measurement and will display all measurements when finished. Also available for measuring the thickness of high temperature surfaces.

Press to confirm selection

Press to Esc. Menu and into the measurement.

7.4.2 Other parameters setting

Press MENU and then press MEM to select the setting

7.4.2.1 Velocity Rate

1. Velocity Setting

Press to select "VEL. SETTING"

There are 9 velocities for materials pre-stored in the gauge. You can select one by pressing SAVE or MEAN

Press key to confirm.

2. Velocity measurement

Measuring a sample which has a known thickness

Press to select "Velocity measurement"

Press or to adjust the value of velocity

Press key to confirm

7.4.2.2 Resolution

Press and select "Resolution"

Press or to select resolution and unit.

0.1 mm 0.01 mm

0.01 mr

0.01 in 0.001 in

Press key to enter/confirm

7.4.2.3 Calibration






Measure the test piece with known thickness.

If the measured value is different to that of the test piece, adjust the measured value by pressing and then press measured value by pressing and then press

The gauge will return to Measurement mode

7.4.3 Memory





1.Memory Unit 2.Delete ALL Memory

7.4.3.1 Memory Unit

The gauge has a memory capacity of 5000 measurements. The memory location is composed of alphabet A-Z and numbers 0000-4999. You can select an Alphabet + an initial number to store the values. The next number being consecutive.

After taking every measurement, press key to store the value with a location number.

7.4.3.2 Memory Read

this initial number.

Press Read (Under the measurement)

In "Memory Read", Press and to select the desired letter.

Press and to select the number. The group value will start from

7.4.3.3 Delete All Memory

Deletes all memory

7.4.4. Date Transfer

Press and select menu.

Press or and select "Date Transfer".

The data can be transferred to a PC using the data view software and can be stored as DOC,TXT or Excel.

For more information, refer to the "Installation Manual" enclosed in the CD

7.4.5 Function

Press and select menu, press or into "FUNCTION", the screen will display:

- 1. Power off
- 2. Gain adjustment
- 3. Default
- 4. Information

Press or to select the item, press to confirm.

7.4.5.1 Power Off

The gauge has an Auto shut down mode after 1 Min. 3 Min. 5 Min. or Never.

7.4.5.2 Gain adjustment

Press and select "Gain adjustment", the screen will display:

- 1. High
- 2. Medium
- 3. Low
- 4. Automatic

Press or to select desired item

Press confirm.

7.4.5.3 Default

When "Default" is selected, the gauge will recover the default parameter.

7.4.5.4 Information

The screen displays the Supplier info. Version number and Transducer Number.

APPENDIX:
SOUND VELOCITY MEASUREMENT CHART (All velocities are approximations)

Material	Sound Velocity		
	Inch/µS	M/s	
Air	0.013	330	
Aluminum	0.250	6300	
Alumina Oxide	0.390	9900	
Beryllium	0.510	12900	
Boron Carbide	0.430	11000	
Brass	0.170	4300	
Cadmium	0.110	2800	
Copper	0.180	4700	
Glass(crown)	0.210	5300	
Glycerin	0.075	1900	
Gold	0.130	3200	
Ice	0.160	4000	
Inconel	0.220	5700	
Iron	0.230	5900	
Iron (cast)	0.180	4600	
Lead	0.085	2200	
Magnesium	0.230	5800	
Mercury	0.057	1400	
Molybdenum	0.250	6300	
Monel	0.210	5400	
Neoprene	0.063	1600	
Nickel	0.220	5600	
Nylon, 6.6	0.100	2600	
Oil (SAE 30)	0.067	1700	
Platinum	0.130	3300	
Plexiglass	0.110	1700	
Polythylene	0.070	1900	
Polystyrene	0.0930	2400	
Polyurethane	0.0700	1900	
Quartz	0.230	5800	
Rubber, Butyl	0.070	1800	
Silver	0.140	3600	
Steel, Mild	0.233	5920	
Steel, Stainless	0.228	5800	
Teflon	0.060	1400	
Tin	0.130	3300	
Titanium	0.240	6100	
Tungsten	0.200	5200	
Uranium	0.130	3400	
Water	0.584	1480	
Zinc	0.170	4200	





Bowers Measuring Equipment Shanghai Co., Ltd.

8th Building, No. 168 Chengjian Rd Minhang District, Shanghai 201108

P.R.China

Telephone: +86 21 6434 8600

Fax: +86 21 6434 6488

Email: sales@bowers-shanghai.com Website: www.bowers-shanghai.com

